



Local Champion Inspection Results

as of 7/10/2018

Local Stock Division

Stock Car: 301 Status: VIP

Stock Car: 302 Status: VIP

Stock Car: 303 Status: VIP

Stock Car: 304 Status: VIP

Stock Car: 305 Status: VIP

Stock Car: 306 Status: VIP

Stock Car: 307 Status: VIP

Stock Car: 308 Status: VIP

Stock Car: 309 Status: NON-VIP

- Failed item 30. "Screw in nose of the shell, Photo 12.11". Reason -> over size holes in shell

Stock Car: 310 Status: VIP

Stock Car: 311 Status: VIP

Stock Car: 312 Status: VIP

Stock Car: 313 Status: VIP

Stock Car: 314 Status: NON-VIP

- Failed item 15. "Brake pad installed per plans, Photos 7.1 & 7.4". Reason -> new brake pad
- Failed item 17. "Brake pedal hardware per plans, Photos 8.4, 8.12 & 8.18 ". Reason -> remove 1-1/4 washer under brake pedal
- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> remove tape from fixed plate
- Failed item 35. "Shell decals and decorations per plans, Photo 13.1 (all views) ". Reason -> remove wrap from inside of shell

Stock Car: 315 Status: VIP

Stock Car: 316 Status: VIP

Stock Car: 317 Status: VIP

Stock Car: 318 Status: VIP

Stock Car: 319 Status: VIP

Stock Car: 320 Status: VIP

Stock Car: 321 Status: VIP

Stock Car: 323 Status: VIP

Stock Car: 324 Status: VIP

Stock Car: 325 Status: NON-VIP

- Failed item 11. "Steering cable routing per plans, Photos 5.23, 5.26, 5.37(a) & (b) ". Reason -> Steering wrap wrong
- Failed item 14. "Stock radius rod assembly per plans, Photos 6.14, 6.17, 6.21 & 6.24 ". Reason -> bolts upside down
- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> wrong bolts

Stock Car: 326 Status: VIP



Local Champion Inspection Results

as of 7/10/2018

Stock Car: 327 Status: NON-VIP

- Failed item 10. "Steering cable adjusters per plans, Photos 5.17 & 5.31". Reason -> steering cable wrapped wrong
- Failed item 14. "Stock radius rod assembly per plans, Photos 6.14, 6.17, 6.21 & 6.24 ". Reason -> Bolts upside down
- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> center weight wrong bolts
- Failed item 40. "Coatings with tung oil and/or wax, ". Reason -> has been stained
- Failed item 43. "61-1/8" inches kp center to kp center +/- 1/16, ". Reason -> rear stabilizer bolt upside

Stock Car: 328 Status: VIP

Stock Car: 329 Status: VIP

Stock Car: 330 Status: VIP

Stock Car: 331 Status: VIP

Stock Car: 332 Status: NON-VIP

- Failed item 15. "Brake pad installed per plans, Photos 7.1 & 7.4". Reason -> new brake pads
- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> center weight on top of brake pulley washer

Stock Car: 333 Status: VIP

Stock Car: 334 Status: VIP

Stock Car: 335 Status: NON-VIP

- Failed item 11. "Steering cable routing per plans, Photos 5.23, 5.26, 5.37(a) & (b) ". Reason -> Steering wrapped wrong

Stock Car: 336 Status: VIP

Stock Car: 337 Status: VIP

Stock Car: 338 Status: VIP

Stock Car: 339 Status: VIP

Stock Car: 341 Status: VIP

Stock Car: 342 Status: VIP

Stock Car: 343 Status: VIP

Stock Car: 344 Status: VIP

Stock Car: 345 Status: NON-VIP

- Failed item 42. "2000 or newer. 7-15/16 maximum nose to kingpin center, ". Reason -> altered axles need to be replaced

Stock Car: 346 Status: VIP

Stock Car: 347 Status: VIP

Stock Car: 348 Status: VIP

Stock Car: 349 Status: VIP

Stock Car: 350 Status: VIP

Stock Car: 351 Status: VIP

Stock Car: 352 Status: VIP

Stock Car: 353 Status: VIP



Local Champion Inspection Results

as of 7/10/2018

Stock Car: 354 Status: NON-VIP

- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> not per plan
- Failed item 28. "Front foam installed per plans, Photo 12.4 ". Reason -> shell cut out covered with tape

Stock Car: 355 Status: VIP

Stock Car: 356 Status: VIP

Stock Car: 357 Status: VIP

Stock Car: 358 Status: VIP

Stock Car: 359 Status: VIP

Stock Car: 360 Status: VIP

Stock Car: 361 Status: NON-VIP

- Failed item 11. "Steering cable routing per plans, Photos 5.23, 5.26, 5.37(a) & (b) ". Reason -> wrong steering wrap
- Failed item 22. "Brake cable routing per plans, Photos 8.46 & 8.49 ". Reason -> no N washer on brake pulley

Stock Car: 362 Status: VIP

Stock Car: 363 Status: VIP

Stock Car: 364 Status: VIP

Stock Car: 365 Status: VIP

Stock Car: 366 Status: VIP

Stock Car: 367 Status: VIP

Stock Car: 368 Status: VIP

Stock Car: 369 Status: NON-VIP

- Failed item 4. "Front kingpin washer stack per plans , Photo 3.17". Reason -> wrong 2" washer
- Failed item 5. "Rear kingpin washer stack per plans, Photo 3.19 ". Reason -> wrong 2" washer
- Failed item 22. "Brake cable routing per plans, Photos 8.46 & 8.49 ". Reason -> no N washer on brake pulley

Stock Car: 370 Status: VIP

Stock Car: 371 Status: VIP

Stock Car: 372 Status: VIP

Stock Car: 373 Status: VIP

Stock Car: 374 Status: VIP

Stock Car: 375 Status: VIP

Stock Car: 376 Status: VIP

Stock Car: 377 Status: VIP

Stock Car: 378 Status: VIP

Stock Car: 379 Status: VIP

Stock Car: 382 Status: VIP

Stock Car: 383 Status: VIP

Stock Car: 384 Status: VIP

Stock Car: 385 Status: VIP

Stock Car: 386 Status: VIP

Stock Car: 387 Status: VIP

Stock Car: 388 Status: VIP



Local Champion Inspection Results

as of 7/10/2018

Local Super Stock Division

Super Stock Car: 101 Status: VIP

Super Stock Car: 102 Status: VIP

Super Stock Car: 103 Status: VIP

Super Stock Car: 104 Status: VIP

Super Stock Car: 105 Status: VIP

Super Stock Car: 106 Status: VIP

Super Stock Car: 107 Status: NON-VIP

- Failed item 40. "Coatings with tung oil and or wax , ". Reason -> unused holes filled

Super Stock Car: 108 Status: VIP

Super Stock Car: 109 Status: VIP

Super Stock Car: 110 Status: VIP

Super Stock Car: 111 Status: NON-VIP

- Failed item 33. "No overspray on inside of shell, ". Reason -> remove paint inside shell

Super Stock Car: 112 Status: VIP

Super Stock Car: 113 Status: VIP

Super Stock Car: 114 Status: NON-VIP

- Failed item 1. "Steering stop hardware per plans, Photo 1.3". Reason -> replace stop bolts not AA
- Failed item 4. "Front kingpin washer stack per plans , Photo 3.17". Reason -> missing 1 14 washer
- Failed item 7. "Cable pulleys installed per plans, Photos 4.13(a) & (b)". Reason -> trim bolts under legs
- Failed item 10. "Steering cable adjusters per plans, Photos 5.17 & 5.31". Reason -> not AA issue replace

Super Stock Car: 115 Status: VIP

Super Stock Car: 116 Status: VIP

Super Stock Car: 117 Status: VIP

Super Stock Car: 118 Status: NON-VIP

- Failed item 11. "Steering cable routing per plans, Photos 5.23, 5.26, 5.37(a) & (b) ". Reason -> not per plan

Super Stock Car: 119 Status: VIP

Super Stock Car: 120 Status: VIP

Super Stock Car: 121 Status: NON-VIP

- Failed item 23. "Adjustable weight hardware per plans, Photo 9.10". Reason -> need dowels in all weights
- Failed item 26. "Front axle plastic airfoils installed per plans, Photos 10.1 & 10.3 ". Reason -> need to be cut straight

Super Stock Car: 122 Status: VIP

Super Stock Car: 123 Status: VIP

Super Stock Car: 124 Status: VIP

Super Stock Car: 125 Status: VIP

Super Stock Car: 126 Status: VIP

Super Stock Car: 127 Status: VIP



Local Champion Inspection Results

as of 7/10/2018

- Super Stock Car: 128 Status: VIP
Super Stock Car: 129 Status: VIP
Super Stock Car: 130 Status: VIP
Super Stock Car: 131 Status: VIP
Super Stock Car: 132 Status: VIP
Super Stock Car: 133 Status: VIP
Super Stock Car: 134 Status: VIP
Super Stock Car: 135 Status: NON-VIP
- Failed item 40. "Coatings with tung oil and or wax , ". Reason -> unused holes have been filled-
remove
- Super Stock Car: 136 Status: VIP
Super Stock Car: 137 Status: VIP
Super Stock Car: 138 Status: VIP
Super Stock Car: 139 Status: VIP
Super Stock Car: 140 Status: VIP
Super Stock Car: 141 Status: VIP
Super Stock Car: 142 Status: VIP
Super Stock Car: 143 Status: VIP
Super Stock Car: 144 Status: VIP
Super Stock Car: 145 Status: VIP
Super Stock Car: 146 Status: VIP
Super Stock Car: 147 Status: NON-VIP
- Failed item 14. "Stabilizer assembly per plans, Photos 6.18 - 6.30 ". Reason -> not AA parts
 - Failed item 18. "Cable pulley installed per plans, Photo 8.25". Reason -> missing lock washer
- Super Stock Car: 148 Status: NON-VIP
- Failed item 14. "Stabilizer assembly per plans, Photos 6.18 - 6.30 ". Reason -> missing n
washers
- Super Stock Car: 149 Status: VIP
Super Stock Car: 150 Status: VIP
Super Stock Car: 151 Status: VIP
Super Stock Car: 152 Status: NON-VIP
- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> no weight in car not
race ready
 - Failed item 25. "Ten pounds of adjustable weight with wing nut, ". Reason -> no weight in car
- Super Stock Car: 153 Status: VIP
Super Stock Car: 154 Status: VIP
Super Stock Car: 155 Status: VIP
Super Stock Car: 156 Status: VIP
Super Stock Car: 157 Status: VIP
Super Stock Car: 158 Status: VIP
Super Stock Car: 159 Status: VIP
Super Stock Car: 160 Status: VIP
Super Stock Car: 161 Status: VIP
Super Stock Car: 162 Status: VIP



Local Champion Inspection Results

as of 7/10/2018

Super Stock Car: 163 Status: VIP

Super Stock Car: 164 Status: VIP

Super Stock Car: 165 Status: VIP

Super Stock Car: 166 Status: VIP

Super Stock Car: 167 Status: VIP

Super Stock Car: 168 Status: VIP

Super Stock Car: 169 Status: VIP

Super Stock Car: 170 Status: NON-VIP

- Failed item 17. "Brake pedal hardware per plans, Photos 8.4, 8.12 & 8.19 ". Reason -> missing two bolts and lock washer on brake pedal

Super Stock Car: 171 Status: VIP

Super Stock Car: 172 Status: NON-VIP

- Failed item 14. "Stabilizer assembly per plans, Photos 6.18 - 6.30 ". Reason -> missing lock washers
- Failed item 17. "Brake pedal hardware per plans, Photos 8.4, 8.12 & 8.19 ". Reason -> missing 1 1/4 washer

Super Stock Car: 173 Status: VIP

Super Stock Car: 174 Status: VIP

Super Stock Car: 175 Status: VIP

Super Stock Car: 177 Status: NON-VIP

- Failed item 14. "Stabilizer assembly per plans, Photos 6.18 - 6.30 ". Reason -> missing 2 inch washers

Super Stock Car: 178 Status: VIP

Super Stock Car: 179 Status: NON-VIP

- Failed item 14. "Stabilizer assembly per plans, Photos 6.18 - 6.30 ". Reason -> missing 2 inch washers

Super Stock Car: 180 Status: VIP

Super Stock Car: 181 Status: VIP

Super Stock Car: 182 Status: VIP

Super Stock Car: 183 Status: VIP



Local Champion Inspection Results

as of 7/10/2018

Local Masters Divisions

Masters Car: 1 Status: VIP

Masters Car: 2 Status: VIP

Masters Car: 3 Status: VIP

Masters Car: 4 Status: NON-VIP

- Failed item 30. "Foils, AASBD issued". Reason -> change air foil attachment
- Failed item 33. "Adjustable, 10 pounds minimum (with wing nuts)". Reason -> need washers on weight bolt

Masters Car: 5 Status: VIP

Masters Car: 6 Status: VIP

Masters Car: 7 Status: VIP

Masters Car: 8 Status: NON-VIP

- Failed item 13. "Shape, No alterations". Reason -> seat back; has to be corrected
- Failed item 32. "Bolts, 5/16 inch bolts". Reason -> s; bottom two are 12- 1/8

Masters Car: 9 Status: VIP

Masters Car: 10 Status: VIP

Masters Car: 11 Status: VIP

Masters Car: 12 Status: VIP

Masters Car: 13 Status: VIP

Masters Car: 14 Status: VIP

Masters Car: 15 Status: VIP

Masters Car: 16 Status: VIP

Masters Car: 17 Status: VIP

Masters Car: 18 Status: VIP

Masters Car: 19 Status: VIP

Masters Car: 20 Status: NON-VIP

- Failed item 24. "Brake Facing, New AASBD brake pad installed". Reason -> need brake pad
- Failed item 30. "Foils, AASBD issued". Reason -> Need screws not bolts

Masters Car: 21 Status: VIP

Masters Car: 22 Status: VIP

Masters Car: 23 Status: VIP

Masters Car: 24 Status: VIP

Masters Car: 25 Status: VIP

Masters Car: 26 Status: VIP

Masters Car: 27 Status: VIP

Masters Car: 28 Status: VIP

Masters Car: 29 Status: VIP

Masters Car: 30 Status: VIP

Masters Car: 31 Status: VIP

Masters Car: 32 Status: VIP

Masters Car: 33 Status: VIP

Masters Car: 34 Status: VIP



Local Champion Inspection Results

as of 7/10/2018

Masters Car: 35 Status: NON-VIP

- Failed item 20. "Attachments, Cable clamps & eyebolts must be visible at axle without removal of any parts". Reason -> wrong eye bolts
- Failed item 27. "Date, 2004 to present". Reason -> F2002 R03 out dated
- Failed item 33. "Adjustable, 10 pounds minimum (with wing nuts)". Reason -> cut or cover rear wgt. bolt

Masters Car: 37 Status: VIP

Masters Car: 38 Status: VIP

Masters Car: 40 Status: NON-VIP

- Failed item 27. "Date, 2004 to present". Reason -> Altered axels need to replace

Masters Car: 41 Status: VIP

Masters Car: 42 Status: VIP

Masters Car: 43 Status: VIP