



2019 Local Champion Inspection Results

as of 7/10/2019

Local Masters Division

Local Masters Car: 1 Status: NON VIP

- Failed item 13. "Shape, No alterations". Reason -> change T-nuts to outside of floorboard

Local Masters Car: 2 Status: VIP

Local Masters Car: 3 Status: NON VIP

- Failed item 33. "Adjustable, 10 pounds minimum (with wing nuts)". Reason -> wedge weights in tale touch body

Local Masters Car: 4 Status: VIP

Local Masters Car: 5 Status: VIP

Local Masters Car: 6 Status: NON VIP

- Failed item 32. "Bolts, 5/16 inch bolts". Reason -> all weight needs to be broken loose
- Failed item 33. "Adjustable, 10 pounds minimum (with wing nuts)". Reason -> put foam on rear adj. weight bolt, 3 bolts not allowed in rear plate, bolt too long

Local Masters Car: 7 Status: NON VIP

- Failed item 30. "Foils, AASBD issued". Reason -> Front axle cover attached with 4 screws - 2 allowed

Local Masters Car: 8 Status: VIP

Local Masters Car: 9 Status: VIP

Local Masters Car: 11 Status: NON VIP

- Failed item 29. "Kingpins, 3-1/2" or 3-1/4" inch grade 8 and must be visible". Reason -> washer stack (more than 3

Local Masters Car: 12 Status: VIP

Local Masters Car: 13 Status: VIP

Local Masters Car: 14 Status: VIP

Local Masters Car: 15 Status: VIP

Local Masters Car: 16 Status: VIP

Local Masters Car: 17 Status: VIP

Local Masters Car: 18 Status: VIP

Local Masters Car: 19 Status: NON VIP

- Failed item 9. "Hinge, AASBD issued". Reason -> Need to cut off excess - hinge screws
- Failed item 30. "Foils, AASBD issued". Reason -> not pins. no tape
- Failed item 31. "Mountings, Four 3/16 inch holes per axle". Reason -> Need approved air foil screws

Local Masters Car: 20 Status: VIP

Local Masters Car: 21 Status: VIP

Local Masters Car: 22 Status: VIP

Local Masters Car: 23 Status: VIP

Local Masters Car: 24 Status: VIP

Local Masters Car: 25 Status: VIP

Local Masters Car: 26 Status: VIP

Local Masters Car: 27 Status: VIP

Local Masters Car: 28 Status: VIP

Local Masters Car: 29 Status: VIP

Local Masters Car: 30 Status: VIP



2019 Local Champion Inspection Results

as of 7/10/2019

Local Masters Car: 31 Status: VIP
Local Masters Car: 32 Status: VIP
Local Masters Car: 33 Status: VIP
Local Masters Car: 34 Status: VIP
Local Masters Car: 35 Status: VIP
Local Masters Car: 36 Status: VIP
Local Masters Car: 38 Status: VIP
Local Masters Car: 40 Status: VIP
Local Masters Car: 42 Status: VIP



2019 Local Champion Inspection Results

as of 7/10/2019

Local Super Stock Division

Local Super Stock Car: 101 Status: VIP

Local Super Stock Car: 102 Status: NON VIP

- Failed item 6. "Steering hardware per plans, Photos 4.7, 4.19, & 4.13(a) & (b)". Reason -> missing nuts
- Failed item 8. "Cable pulley hardware per plans, Photo 5.5". Reason -> missing N washer
- Failed item 13. "Bushing installed per plans, Photos 6.6 & 6.8". Reason -> missing 2" washer
- Failed item 18. "Cable pulley installed per plans, Photo 8.25". Reason -> missing N washers
- Failed item 23. "Adjustable weight hardware per plans, Photo 9.10". Reason -> missing plug in bar bell
- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> cut bolts

Local Super Stock Car: 103 Status: VIP

Local Super Stock Car: 104 Status: VIP

Local Super Stock Car: 105 Status: NON VIP

- Failed item 9. "Axle eyebolt per plans, Photo 5.12". Reason -> Rear axle mount needs washers underneath axle
- Failed item 16. "New brake pad installed, ". Reason -> needs new brake pad, change foot brace
- Failed item 17. "Brake pedal hardware per plans, Photos 8.4, 8.12 & 8.19". Reason -> needs lockwasher for eyebolt
- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> weights too long, are backwards
- Failed item 26. "Front axle plastic airfoils installed per plans, Photos 10.1 & 10.3". Reason -> swap airfoils

Local Super Stock Car: 106 Status: NON VIP

- Failed item 14. "Stabilizer assembly per plans, Photos 6.18 - 6.30". Reason -> missing 2" washer on rear stabilizer

Local Super Stock Car: 107 Status: VIP

Local Super Stock Car: 108 Status: VIP

Local Super Stock Car: 109 Status: VIP

Local Super Stock Car: 110 Status: VIP

Local Super Stock Car: 111 Status: VIP

Local Super Stock Car: 112 Status: VIP

Local Super Stock Car: 113 Status: NON VIP

- Failed item 2. "Foot brace hardware per plans, Photo 2.4". Reason -> Has been cut - replace
- Failed item 14. "Stabilizer assembly per plans, Photos 6.18 - 6.30". Reason -> bolt too short
- Failed item 17. "Brake pedal hardware per plans, Photos 8.4, 8.12 & 8.19". Reason -> Washer on wrong side of bolt

Local Super Stock Car: 114 Status: VIP

Local Super Stock Car: 115 Status: VIP

Local Super Stock Car: 117 Status: NON VIP

- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> Wrong bolts - 1/4
- Failed item 28. "Front foam installed per plans, Photo 12.4". Reason -> remove side and rear form - been altered

Local Super Stock Car: 118 Status: VIP



2019 Local Champion Inspection Results

as of 7/10/2019

Local Super Stock Car: 119 Status: VIP

Local Super Stock Car: 120 Status: VIP

Local Super Stock Car: 121 Status: VIP

Local Super Stock Car: 122 Status: VIP

Local Super Stock Car: 123 Status: VIP

Local Super Stock Car: 124 Status: VIP

Local Super Stock Car: 125 Status: NON VIP

- Failed item 8. "Cable pulley hardware per plans, Photo 5.5 ". Reason -> No N washers
- Failed item 43. "63-3/8" inches kingpin center to kingpin center +/- 1/16", ". Reason -> Missing

2

Local Super Stock Car: 126 Status: VIP

Local Super Stock Car: 127 Status: VIP

Local Super Stock Car: 128 Status: VIP

Local Super Stock Car: 129 Status: VIP

Local Super Stock Car: 130 Status: VIP

Local Super Stock Car: 131 Status: VIP

Local Super Stock Car: 132 Status: VIP

Local Super Stock Car: 133 Status: VIP

Local Super Stock Car: 134 Status: VIP

Local Super Stock Car: 135 Status: VIP

Local Super Stock Car: 136 Status: VIP

Local Super Stock Car: 137 Status: VIP

Local Super Stock Car: 138 Status: VIP

Local Super Stock Car: 139 Status: VIP

Local Super Stock Car: 140 Status: VIP

Local Super Stock Car: 141 Status: VIP

Local Super Stock Car: 142 Status: VIP

Local Super Stock Car: 143 Status: VIP

Local Super Stock Car: 144 Status: VIP

Local Super Stock Car: 145 Status: VIP

Local Super Stock Car: 146 Status: VIP

Local Super Stock Car: 147 Status: VIP

Local Super Stock Car: 148 Status: VIP

Local Super Stock Car: 149 Status: VIP

Local Super Stock Car: 150 Status: VIP

Local Super Stock Car: 151 Status: VIP

Local Super Stock Car: 152 Status: VIP

Local Super Stock Car: 153 Status: VIP

Local Super Stock Car: 154 Status: VIP

Local Super Stock Car: 155 Status: VIP

Local Super Stock Car: 156 Status: VIP

Local Super Stock Car: 157 Status: VIP

Local Super Stock Car: 158 Status: VIP

Local Super Stock Car: 159 Status: VIP

Local Super Stock Car: 160 Status: VIP

Local Super Stock Car: 161 Status: VIP



2019 Local Champion Inspection Results

as of 7/10/2019

Local Super Stock Car: 162 Status: VIP

Local Super Stock Car: 163 Status: VIP

Local Super Stock Car: 164 Status: VIP

Local Super Stock Car: 165 Status: VIP

Local Super Stock Car: 166 Status: VIP

Local Super Stock Car: 167 Status: VIP

Local Super Stock Car: 168 Status: VIP

Local Super Stock Car: 169 Status: VIP

Local Super Stock Car: 170 Status: VIP

Local Super Stock Car: 171 Status: VIP

Local Super Stock Car: 172 Status: VIP

Local Super Stock Car: 173 Status: VIP

Local Super Stock Car: 174 Status: VIP

Local Super Stock Car: 175 Status: VIP

Local Super Stock Car: 176 Status: VIP

Local Super Stock Car: 177 Status: VIP

Local Super Stock Car: 178 Status: VIP

Local Super Stock Car: 179 Status: VIP

Local Super Stock Car: 180 Status: VIP

Local Super Stock Car: 181 Status: NON VIP

- Failed item 12. "Cable double-clamped per plans, Photo 5.36". Reason -> missing 4 N washers on steering plate
- Failed item 18. "Cable pulley installed per plans, Photo 8.25". Reason -> missing 4 N washers on brake pulley

Local Super Stock Car: 183 Status: NON VIP

- Failed item 16. "New brake pad installed, ". Reason -> needs new brake pad
- Failed item 23. "Adjustable weight hardware per plans, Photo 9.10". Reason -> Barbel weights need dowl rods in middle

Local Super Stock Car: 184 Status: VIP

Local Super Stock Car: 185 Status: NON VIP

- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> too long
- Failed item 40. "Coatings with tung oil and or wax , ". Reason -> Remove all tape from floorboard

Local Super Stock Car: 186 Status: VIP

Local Super Stock Car: 187 Status: NON VIP

- Failed item 13. "Bushing installed per plans, Photos 6.6 & 6.8". Reason -> Rear stabillizer locker washer in wrong position



2019 Local Champion Inspection Results

as of 7/10/2019

Local Stock Division

Local Stock Car: 301 Status: VIP

Local Stock Car: 302 Status: VIP

Local Stock Car: 304 Status: VIP

Local Stock Car: 305 Status: VIP

Local Stock Car: 306 Status: VIP

Local Stock Car: 308 Status: VIP

Local Stock Car: 309 Status: VIP

Local Stock Car: 310 Status: VIP

Local Stock Car: 311 Status: VIP

Local Stock Car: 312 Status: NON VIP

- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> too long

Local Stock Car: 313 Status: VIP

Local Stock Car: 314 Status: VIP

Local Stock Car: 315 Status: VIP

Local Stock Car: 316 Status: VIP

Local Stock Car: 317 Status: VIP

Local Stock Car: 318 Status: NON VIP

- Failed item 14. "Stock radius rod assembly per plans, Photos 6.14, 6.17, 6.21 & 6.24 ". Reason -> bolts upside down
- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> Replace weight bolts/currently quarter inch

Local Stock Car: 319 Status: VIP

Local Stock Car: 320 Status: NON VIP

- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> weight too long, long weight bolts

Local Stock Car: 321 Status: VIP

Local Stock Car: 322 Status: VIP

Local Stock Car: 323 Status: VIP

Local Stock Car: 324 Status: VIP

Local Stock Car: 325 Status: VIP

Local Stock Car: 326 Status: VIP

Local Stock Car: 327 Status: VIP

Local Stock Car: 328 Status: VIP

Local Stock Car: 329 Status: VIP

Local Stock Car: 330 Status: VIP

Local Stock Car: 331 Status: VIP

Local Stock Car: 332 Status: VIP

Local Stock Car: 333 Status: VIP

Local Stock Car: 335 Status: VIP

Local Stock Car: 336 Status: VIP

Local Stock Car: 338 Status: NON VIP

- Failed item 8. "Cable pulley hardware per plans, Photo 5.5 ". Reason -> steering too loose

Local Stock Car: 339 Status: VIP

Local Stock Car: 340 Status: VIP



2019 Local Champion Inspection Results

as of 7/10/2019

Local Stock Car: 342 Status: VIP

Local Stock Car: 343 Status: VIP

Local Stock Car: 344 Status: VIP

Local Stock Car: 345 Status: VIP

Local Stock Car: 346 Status: VIP

Local Stock Car: 347 Status: VIP

Local Stock Car: 348 Status: NON VIP

- Failed item 13. "Bushing installed per plans, Photos 6.5 & 6.7". Reason -> Wrong bolts in stabilizer
- Failed item 23. "Adjustable weight hardware per plans, Photo 9.10". Reason -> front weight bolt been cut off
- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> need to grind off

Local Stock Car: 349 Status: VIP

Local Stock Car: 350 Status: VIP

Local Stock Car: 351 Status: VIP

Local Stock Car: 352 Status: NON VIP

- Failed item 4. "Front kingpin washer stack per plans , Photo 3.17". Reason -> Missing 2

Local Stock Car: 353 Status: VIP

Local Stock Car: 354 Status: VIP

Local Stock Car: 355 Status: VIP

Local Stock Car: 356 Status: VIP

Local Stock Car: 357 Status: VIP

Local Stock Car: 358 Status: VIP

Local Stock Car: 359 Status: VIP

Local Stock Car: 360 Status: VIP

Local Stock Car: 361 Status: VIP

Local Stock Car: 362 Status: VIP

Local Stock Car: 364 Status: VIP

Local Stock Car: 365 Status: VIP

Local Stock Car: 366 Status: VIP

Local Stock Car: 367 Status: VIP

Local Stock Car: 368 Status: VIP

Local Stock Car: 369 Status: VIP

Local Stock Car: 370 Status: VIP

Local Stock Car: 371 Status: VIP

Local Stock Car: 372 Status: VIP

Local Stock Car: 373 Status: VIP

Local Stock Car: 374 Status: VIP

Local Stock Car: 375 Status: VIP

Local Stock Car: 376 Status: VIP

Local Stock Car: 377 Status: VIP

Local Stock Car: 378 Status: VIP

Local Stock Car: 379 Status: VIP

Local Stock Car: 380 Status: VIP

Local Stock Car: 381 Status: VIP

Local Stock Car: 382 Status: VIP



2019 Local Champion Inspection Results

as of 7/10/2019

Local Stock Car: 383 Status: VIP

Local Stock Car: 384 Status: NON VIP

- Failed item 6. "Steering hardware per plans, Photos 4.7, 4.19, & 4.13(a) & (b)". Reason -> No N washers
- Failed item 18. "Cable pulley installed per plans, Photo 8.24". Reason -> Bolts wrong, missing N washers

Local Stock Car: 386 Status: NON VIP

- Failed item 14. "Stock radius rod assembly per plans, Photos 6.14, 6.17, 6.21 & 6.24". Reason -> rear bolts need 2 N washer rear bolts need flipped over
- Failed item 17. "Brake pedal hardware per plans, Photos 8.4, 8.12 & 8.18". Reason -> needs 2 N washers on front

Local Stock Car: 387 Status: NON VIP

- Failed item 14. "Stock radius rod assembly per plans, Photos 6.14, 6.17, 6.21 & 6.24". Reason -> too many rear stabilizer washe. no 2

Local Stock Car: 388 Status: VIP

Local Stock Car: 389 Status: VIP

Local Stock Car: 390 Status: VIP