



## 2019 Rally Champion Inspection Results

as of 7/10/2019

### Rally Masters Division

**Rally Masters Car: 500 Status: VIP**

**Rally Masters Car: 501 Status: VIP**

**Rally Masters Car: 502 Status: VIP**

**Rally Masters Car: 503 Status: VIP**

**Rally Masters Car: 504 Status: NON VIP**

- Failed item 33. "Adjustable, 10 pounds minimum (with wing nuts)". Reason -> Rear weight stack not clearing the body

**Rally Masters Car: 505 Status: VIP**

**Rally Masters Car: 506 Status: NON VIP**

- Failed item 17. "Kingpins, AASBD issued kingpins and bushings only". Reason -> maxium kingpin stack on front axle needs to be 3
- Failed item 33. "Adjustable, 10 pounds minimum (with wing nuts)". Reason -> no gaps between weights, does not meet 3

**Rally Masters Car: 507 Status: VIP**

**Rally Masters Car: 508 Status: VIP**

**Rally Masters Car: 509 Status: NON VIP**

- Failed item 5. "Helmet, First rivit must be visible". Reason -> not 7" wide from first rivet forward

**Rally Masters Car: 510 Status: VIP**

**Rally Masters Car: 511 Status: VIP**

**Rally Masters Car: 512 Status: VIP**

**Rally Masters Car: 513 Status: VIP**

**Rally Masters Car: 514 Status: VIP**

**Rally Masters Car: 515 Status: VIP**

**Rally Masters Car: 516 Status: VIP**

**Rally Masters Car: 517 Status: VIP**

**Rally Masters Car: 518 Status: VIP**

**Rally Masters Car: 520 Status: VIP**

**Rally Masters Car: 521 Status: VIP**

**Rally Masters Car: 522 Status: VIP**

**Rally Masters Car: 523 Status: VIP**

**Rally Masters Car: 524 Status: NON VIP**

- Failed item 33. "Adjustable, 10 pounds minimum (with wing nuts)". Reason -> Chained/overlapping weights

**Rally Masters Car: 525 Status: VIP**

**Rally Masters Car: 526 Status: VIP**

**Rally Masters Car: 527 Status: VIP**

**Rally Masters Car: 528 Status: VIP**

**Rally Masters Car: 530 Status: VIP**

**Rally Masters Car: 531 Status: VIP**

**Rally Masters Car: 532 Status: VIP**

**Rally Masters Car: 533 Status: VIP**



## 2019 Rally Champion Inspection Results

as of 7/10/2019

**Rally Masters Car: 534 Status: NON VIP**

- Failed item 12. "Foam, AASBD issued foam, 6 inches of foam in front of face". Reason -> 3" axle measurement
- Failed item 14. "Sealer, Tung oil finish and wax". Reason -> remove excessive apoxy around plates

**Rally Masters Car: 535 Status: VIP**

**Rally Masters Car: 536 Status: VIP**

**Rally Masters Car: 537 Status: NON VIP**

- Failed item 15. "Axle Mounting Plates, AASBD issued. AASBD logo must be visible". Reason -> apoxy around plates needs to be removed

**Rally Masters Car: 538 Status: VIP**

**Rally Masters Car: 539 Status: VIP**

**Rally Masters Car: 540 Status: VIP**

**Rally Masters Car: 541 Status: VIP**

**Rally Masters Car: 542 Status: VIP**

**Rally Masters Car: 543 Status: VIP**

**Rally Masters Car: 544 Status: VIP**

**Rally Masters Car: 545 Status: VIP**

**Rally Masters Car: 546 Status: VIP**

**Rally Masters Car: 547 Status: VIP**

**Rally Masters Car: 548 Status: VIP**

**Rally Masters Car: 549 Status: VIP**

**Rally Masters Car: 550 Status: VIP**

**Rally Masters Car: 551 Status: VIP**

**Rally Masters Car: 552 Status: VIP**

**Rally Masters Car: 553 Status: VIP**

**Rally Masters Car: 554 Status: VIP**

**Rally Masters Car: 555 Status: VIP**

**Rally Masters Car: 556 Status: VIP**



## 2019 Rally Champion Inspection Results

as of 7/10/2019

### Rally Super Stock Division

Rally Super Stock Car: 600 Status: VIP  
Rally Super Stock Car: 603 Status: VIP  
Rally Super Stock Car: 604 Status: VIP  
Rally Super Stock Car: 605 Status: VIP  
Rally Super Stock Car: 606 Status: VIP  
Rally Super Stock Car: 607 Status: VIP  
Rally Super Stock Car: 608 Status: VIP  
Rally Super Stock Car: 609 Status: VIP  
Rally Super Stock Car: 610 Status: VIP  
Rally Super Stock Car: 612 Status: VIP  
Rally Super Stock Car: 615 Status: VIP  
Rally Super Stock Car: 616 Status: VIP  
Rally Super Stock Car: 617 Status: VIP  
Rally Super Stock Car: 618 Status: VIP  
Rally Super Stock Car: 619 Status: VIP  
Rally Super Stock Car: 620 Status: VIP  
Rally Super Stock Car: 621 Status: VIP  
Rally Super Stock Car: 622 Status: VIP  
Rally Super Stock Car: 623 Status: VIP  
Rally Super Stock Car: 624 Status: VIP  
Rally Super Stock Car: 626 Status: VIP  
Rally Super Stock Car: 627 Status: VIP  
Rally Super Stock Car: 628 Status: VIP  
Rally Super Stock Car: 629 Status: VIP  
Rally Super Stock Car: 630 Status: VIP  
Rally Super Stock Car: 631 Status: VIP  
Rally Super Stock Car: 632 Status: VIP  
Rally Super Stock Car: 633 Status: VIP  
Rally Super Stock Car: 634 Status: VIP  
Rally Super Stock Car: 635 Status: VIP  
Rally Super Stock Car: 636 Status: VIP  
Rally Super Stock Car: 637 Status: VIP  
Rally Super Stock Car: 638 Status: NON VIP

- Failed item 13. "Bushing installed per plans, Photos 6.6 & 6.8". Reason -> Remove lock washers from rear stabilizer

Rally Super Stock Car: 639 Status: VIP  
Rally Super Stock Car: 640 Status: VIP  
Rally Super Stock Car: 641 Status: VIP  
Rally Super Stock Car: 642 Status: VIP  
Rally Super Stock Car: 643 Status: VIP  
Rally Super Stock Car: 644 Status: VIP  
Rally Super Stock Car: 645 Status: VIP



## 2019 Rally Champion Inspection Results

as of 7/10/2019

**Rally Super Stock Car: 646 Status: VIP**

**Rally Super Stock Car: 647 Status: VIP**

**Rally Super Stock Car: 648 Status: VIP**

**Rally Super Stock Car: 649 Status: VIP**

**Rally Super Stock Car: 650 Status: NON VIP**

- Failed item 4. "Front kingpin washer stack per plans , Photo 3.17". Reason -> Needs second lock nut
- Failed item 5. "Rear kingpin washer stack per plans, Photo 3.26 ". Reason -> Needs 2" washers on top
- Failed item 17. "Brake pedal hardware per plans, Photos 8.4, 8.12 & 8.19 ". Reason -> Needs a nut and lockwasher on eyebolt

**Rally Super Stock Car: 651 Status: VIP**



## 2019 Rally Champion Inspection Results

as of 7/10/2019

### Rally Stock Division

**Rally Stock Car: 700 Status: VIP**

**Rally Stock Car: 701 Status: NON VIP**

- Failed item 5. "Rear kingpin washer stack per plans, Photo 3.19 ". Reason -> No 2" washer on rear kingpin
- Failed item 11. "Steering cable routing per plans, Photos 5.23, 5.26, 5.37(a) & (b) ". Reason -> too much tape on steering cable
- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> middle weight bolt needs cut

**Rally Stock Car: 702 Status: VIP**

**Rally Stock Car: 703 Status: VIP**

**Rally Stock Car: 704 Status: VIP**

**Rally Stock Car: 705 Status: VIP**

**Rally Stock Car: 706 Status: VIP**

**Rally Stock Car: 707 Status: VIP**

**Rally Stock Car: 708 Status: NON VIP**

- Failed item 16. "New brake pad installed, ". Reason -> Needs a new brake pad
- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> Bolts need to be cut

**Rally Stock Car: 709 Status: VIP**

**Rally Stock Car: 710 Status: NON VIP**

- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> too long
- Failed item 34. "Holes in shell for attachment to floorboard must not be altered, ". Reason -> shell has been altered

**Rally Stock Car: 711 Status: VIP**

**Rally Stock Car: 712 Status: VIP**

**Rally Stock Car: 713 Status: VIP**

**Rally Stock Car: 714 Status: VIP**

**Rally Stock Car: 715 Status: VIP**

**Rally Stock Car: 716 Status: VIP**

**Rally Stock Car: 717 Status: VIP**

**Rally Stock Car: 719 Status: VIP**

**Rally Stock Car: 720 Status: VIP**

**Rally Stock Car: 721 Status: VIP**

**Rally Stock Car: 722 Status: VIP**

**Rally Stock Car: 723 Status: VIP**

**Rally Stock Car: 724 Status: VIP**

**Rally Stock Car: 725 Status: VIP**

**Rally Stock Car: 726 Status: VIP**

**Rally Stock Car: 727 Status: VIP**

**Rally Stock Car: 728 Status: VIP**

**Rally Stock Car: 729 Status: VIP**

**Rally Stock Car: 730 Status: VIP**



## 2019 Rally Champion Inspection Results

as of 7/10/2019

Rally Stock Car: 731 Status: VIP

Rally Stock Car: 732 Status: VIP

Rally Stock Car: 733 Status: VIP

Rally Stock Car: 734 Status: VIP

Rally Stock Car: 735 Status: VIP

Rally Stock Car: 736 Status: VIP

Rally Stock Car: 737 Status: VIP

Rally Stock Car: 738 Status: VIP

Rally Stock Car: 739 Status: VIP

Rally Stock Car: 740 Status: VIP

Rally Stock Car: 742 Status: VIP

Rally Stock Car: 743 Status: VIP

Rally Stock Car: 744 Status: VIP

Rally Stock Car: 745 Status: VIP

Rally Stock Car: 747 Status: VIP

Rally Stock Car: 748 Status: VIP

Rally Stock Car: 749 Status: VIP

Rally Stock Car: 750 Status: VIP

Rally Stock Car: 751 Status: VIP

Rally Stock Car: 752 Status: VIP

Rally Stock Car: 753 Status: VIP

Rally Stock Car: 754 Status: VIP

Rally Stock Car: 755 Status: VIP

Rally Stock Car: 756 Status: VIP

Rally Stock Car: 757 Status: VIP

Rally Stock Car: 758 Status: NON VIP

- Failed item 4. "Front kingpin washer stack per plans , Photo 3.17". Reason -> 2" washers under axle missing

Rally Stock Car: 760 Status: NON VIP

- Failed item 15. "Brake pad installed per plans, Photos 7.1 & 7.4". Reason -> Needs new brake pad
- Failed item 29. "Optional rear and side foam installed per plans, Photo E22.5". Reason -> Replace all foam

Rally Stock Car: 761 Status: VIP

Rally Stock Car: 762 Status: VIP

Rally Stock Car: 763 Status: VIP

Rally Stock Car: 764 Status: VIP