



Rally Champion Inspection Results

as of 7/10/2018

Rally Stock Division

Rally Stock Car: 700 Status: VIP

Rally Stock Car: 701 Status: VIP

Rally Stock Car: 702 Status: VIP

Rally Stock Car: 703 Status: VIP

Rally Stock Car: 704 Status: VIP

Rally Stock Car: 705 Status: VIP

Rally Stock Car: 706 Status: VIP

Rally Stock Car: 707 Status: VIP

Rally Stock Car: 708 Status: VIP

Rally Stock Car: 709 Status: NON-VIP

- Failed item 15. "Brake pad installed per plans, Photos 7.1 & 7.4". Reason -> need new brake pad
- Failed item 22. "Brake cable routing per plans, Photos 8.46 & 8.49 ". Reason -> needs N washer on brake pulley
- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> cut weight bolts

Rally Stock Car: 710 Status: VIP

Rally Stock Car: 711 Status: NON-VIP

- Failed item 23. "Adjustable weight hardware per plans, Photo 9.10". Reason -> weights need dowels

Rally Stock Car: 712 Status: VIP

Rally Stock Car: 713 Status: VIP

Rally Stock Car: 714 Status: VIP

Rally Stock Car: 715 Status: VIP

Rally Stock Car: 716 Status: VIP

Rally Stock Car: 717 Status: VIP

Rally Stock Car: 718 Status: NON-VIP

- Failed item 4. "Front kingpin washer stack per plans , Photo 3.17". Reason -> no 2" washer

Rally Stock Car: 719 Status: VIP

Rally Stock Car: 720 Status: VIP

Rally Stock Car: 721 Status: VIP

Rally Stock Car: 722 Status: VIP

Rally Stock Car: 723 Status: VIP

Rally Stock Car: 724 Status: VIP

Rally Stock Car: 725 Status: VIP

Rally Stock Car: 726 Status: VIP

Rally Stock Car: 728 Status: VIP

Rally Stock Car: 729 Status: VIP

Rally Stock Car: 730 Status: VIP

Rally Stock Car: 731 Status: VIP

Rally Stock Car: 732 Status: VIP

Rally Stock Car: 733 Status: VIP

Rally Stock Car: 734 Status: VIP

Rally Stock Car: 735 Status: VIP



Rally Champion Inspection Results

as of 7/10/2018

Rally Stock Car: 736 Status: VIP

Rally Stock Car: 737 Status: VIP

Rally Stock Car: 738 Status: VIP

Rally Stock Car: 739 Status: VIP

Rally Stock Car: 740 Status: VIP

Rally Stock Car: 741 Status: VIP

Rally Stock Car: 742 Status: VIP

Rally Stock Car: 744 Status: NON-VIP

- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> wrong bolts

Rally Stock Car: 745 Status: VIP

Rally Stock Car: 746 Status: VIP

Rally Stock Car: 747 Status: VIP

Rally Stock Car: 748 Status: VIP

Rally Stock Car: 749 Status: VIP

Rally Stock Car: 750 Status: VIP

Rally Stock Car: 751 Status: VIP

Rally Stock Car: 752 Status: VIP

Rally Stock Car: 753 Status: VIP



Rally Champion Inspection Results

as of 7/10/2018

Rally Super Stock Division

Rally Super Stock Car: 600 Status: VIP
Rally Super Stock Car: 601 Status: VIP
Rally Super Stock Car: 602 Status: VIP
Rally Super Stock Car: 603 Status: VIP
Rally Super Stock Car: 604 Status: VIP
Rally Super Stock Car: 605 Status: VIP
Rally Super Stock Car: 606 Status: VIP
Rally Super Stock Car: 607 Status: VIP
Rally Super Stock Car: 608 Status: VIP
Rally Super Stock Car: 609 Status: VIP
Rally Super Stock Car: 610 Status: VIP
Rally Super Stock Car: 611 Status: VIP
Rally Super Stock Car: 612 Status: VIP
Rally Super Stock Car: 613 Status: VIP
Rally Super Stock Car: 614 Status: VIP
Rally Super Stock Car: 615 Status: VIP
Rally Super Stock Car: 609 Status: VIP
Rally Super Stock Car: 610 Status: VIP
Rally Super Stock Car: 611 Status: VIP
Rally Super Stock Car: 612 Status: VIP
Rally Super Stock Car: 613 Status: VIP
Rally Super Stock Car: 614 Status: VIP
Rally Super Stock Car: 615 Status: VIP
Rally Super Stock Car: 616 Status: VIP
Rally Super Stock Car: 609 Status: VIP
Rally Super Stock Car: 610 Status: VIP
Rally Super Stock Car: 611 Status: VIP
Rally Super Stock Car: 612 Status: VIP
Rally Super Stock Car: 613 Status: VIP
Rally Super Stock Car: 614 Status: VIP
Rally Super Stock Car: 615 Status: VIP
Rally Super Stock Car: 616 Status: VIP
Rally Super Stock Car: 617 Status: VIP
Rally Super Stock Car: 618 Status: VIP
Rally Super Stock Car: 619 Status: VIP
Rally Super Stock Car: 621 Status: VIP
Rally Super Stock Car: 623 Status: VIP
Rally Super Stock Car: 624 Status: VIP
Rally Super Stock Car: 625 Status: VIP
Rally Super Stock Car: 626 Status: VIP
Rally Super Stock Car: 627 Status: VIP
Rally Super Stock Car: 628 Status: VIP
Rally Super Stock Car: 629 Status: VIP



Rally Champion Inspection Results

as of 7/10/2018

Rally Super Stock Car: 630 Status: VIP
Rally Super Stock Car: 631 Status: VIP
Rally Super Stock Car: 632 Status: VIP
Rally Super Stock Car: 633 Status: VIP
Rally Super Stock Car: 635 Status: VIP
Rally Super Stock Car: 636 Status: VIP
Rally Super Stock Car: 637 Status: VIP
Rally Super Stock Car: 638 Status: VIP
Rally Super Stock Car: 639 Status: VIP
Rally Super Stock Car: 640 Status: VIP
Rally Super Stock Car: 641 Status: VIP
Rally Super Stock Car: 642 Status: VIP
Rally Super Stock Car: 643 Status: VIP
Rally Super Stock Car: 644 Status: VIP
Rally Super Stock Car: 645 Status: VIP
Rally Super Stock Car: 646 Status: VIP
Rally Super Stock Car: 647 Status: NON-VIP

- Failed item 14. "Stabilizer assembly per plans, Photos 6.18 - 6.30 ". Reason -> replace flat washers not AA issue

Rally Super Stock Car: 648 Status: VIP
Rally Super Stock Car: 649 Status: NON-VIP

- Failed item 15. "Brake pad installed per plans, Photos 7.1 & 7.4". Reason -> need new brake pad
- Failed item 24. "Fixed weight hardware per plans, Photo E20.6". Reason -> cut weight bolts flush

Rally Super Stock Car: 650 Status: VIP
Rally Super Stock Car: 651 Status: VIP
Rally Super Stock Car: 652 Status: VIP
Rally Super Stock Car: 653 Status: VIP
Rally Super Stock Car: 654 Status: VIP
Rally Super Stock Car: 655 Status: VIP



Rally Champion Inspection Results

as of 7/10/2018

Rally Masters Division

Rally Masters Car: 500 Status: NON-VIP

- Failed item 20. "Attachments, Cable clamps & eyebolts must be visible at axle without removal of any parts". Reason -> Steering cable adjusters wrong

Rally Masters Car: 501 Status: VIP

Rally Masters Car: 502 Status: VIP

Rally Masters Car: 503 Status: VIP

Rally Masters Car: 504 Status: VIP

Rally Masters Car: 505 Status: VIP

Rally Masters Car: 506 Status: VIP

Rally Masters Car: 507 Status: VIP

Rally Masters Car: 508 Status: VIP

Rally Masters Car: 509 Status: VIP

Rally Masters Car: 510 Status: VIP

Rally Masters Car: 511 Status: VIP

Rally Masters Car: 512 Status: VIP

Rally Masters Car: 513 Status: VIP

Rally Masters Car: 514 Status: VIP

Rally Masters Car: 515 Status: VIP

Rally Masters Car: 516 Status: VIP

Rally Masters Car: 517 Status: VIP

Rally Masters Car: 518 Status: VIP

Rally Masters Car: 519 Status: VIP

Rally Masters Car: 520 Status: VIP

Rally Masters Car: 521 Status: VIP

Rally Masters Car: 522 Status: VIP

Rally Masters Car: 523 Status: VIP

Rally Masters Car: 524 Status: VIP

Rally Masters Car: 525 Status: VIP

Rally Masters Car: 526 Status: VIP

Rally Masters Car: 527 Status: VIP

Rally Masters Car: 528 Status: VIP

Rally Masters Car: 529 Status: VIP

Rally Masters Car: 530 Status: VIP

Rally Masters Car: 531 Status: VIP

Rally Masters Car: 532 Status: VIP

Rally Masters Car: 533 Status: VIP

Rally Masters Car: 534 Status: NON-VIP

- Failed item 33. "Adjustable, 10 pounds minimum (with wing nuts)". Reason -> wgts over 12 inches

Rally Masters Car: 535 Status: VIP

Rally Masters Car: 536 Status: VIP

Rally Masters Car: 537 Status: VIP

Rally Masters Car: 538 Status: VIP



Rally Champion Inspection Results

as of 7/10/2018

Rally Masters Car: 539 Status: VIP
Rally Masters Car: 540 Status: VIP
Rally Masters Car: 541 Status: VIP
Rally Masters Car: 542 Status: VIP
Rally Masters Car: 543 Status: VIP
Rally Masters Car: 544 Status: VIP
Rally Masters Car: 546 Status: VIP
Rally Masters Car: 547 Status: VIP
Rally Masters Car: 548 Status: VIP
Rally Masters Car: 549 Status: VIP
Rally Masters Car: 550 Status: VIP