

Car No. = 301, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 302, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 303, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 304, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 305, Local, Stock NON VIP

- Failed item 4. "Front kingpin washer stack per plans , Photo 3.20". Reason -> Not per plan
- Failed item 5. "Rear kingpin washer stack per plans, Photo 3.19 ". Reason -> Not per plan
- Failed item 7. "Cable pulleys installed per plans, Photos 5.6". Reason -> Need pulley upgrade
- Failed item 8. "Cable pulley hardware per plans, Photo 5.6 ". Reason -> need up graded
- Failed item 10. "Steering cable adjusters per plans, Photos 5.18". Reason -> need adjusters
- Failed item 11. "Steering cable routing per plans, Photos 5.24, 5.27, 5.38(a) & (b) ". Reason -> noy per plan
- Failed item 13. "Bushing installed per plans, Photos 6.7". Reason -> needs upgrades
- Failed item 18. "Cable pulley installed per plans, Photo 8.24". Reason -> not per plan
- Failed item 20. "Awning pulley hardware per plans, Photo 8.41". Reason -> needs awning pulley
- Failed item 22. "Brake cable routing per plans, Photos 8.47 & 8.50 ". Reason -> notr per plan
- Failed item 28. "Front foam installed per plans, Photo 12.4 ". Reason -> need ASABD foam
- Failed item 30. "Screw in nose of the shell, Photo 12.11". Reason -> needs nose screw
- item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
- item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Failed item 38. "Local Race City Organization OR Rally Region, Photo 13.1 (all views)
". Reason -> needs race city

Car No. = 306, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 307, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 308, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 309, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 310, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 311, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 312, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 313, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 314, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 315, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 316, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 317, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 318, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!

item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 319, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 320, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 321, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 322, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 323, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 324, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 325, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 326, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 327, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 328, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 329, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 330, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 332, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!

item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 333, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 334, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 335, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 336, Local, Stock NON VIP

Failed item 24. "Fixed weight hardware per plans, Photo 1.6". Reason -> WEIGHT TO LONG

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 337, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 338, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 339, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 340, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 341, Local, Stock NON VIP

Failed item 7. "Cable pulleys installed per plans, Photos 5.6". Reason -> Replace 1-1/4 washer with "N" washer

Failed item 24. "Fixed weight hardware per plans, Photo 1.6". Reason -> Weights too long - need to paint lead weights

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 342, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 344, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 345, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 346, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 347, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 348, Local, Stock NON VIP

- Failed item 24. "Fixed weight hardware per plans, Photo 1.6". Reason ->
 - item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
 - Failed item 38. "Local Race City Organization OR Rally Region, Photo 13.1 (all views)" . Reason -> need rece city
-

Car No. = 349, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 350, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 351, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 352, Local, Stock VIP But the following will be checked after shell

installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 353, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 354, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 355, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 356, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 357, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = 358, Local, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
- item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
- item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 359, Local, Stock NON VIP

Failed item 15. "Brake pad installed per plans, Photos 7.1 & 7.4". Reason -> tighten brake cable

Failed item 26. "Front axle plastic airfoils installed per plans, Photos 10.1 & 10.3 ". Reason -> Needs airfoils

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!

item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!

item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 360, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!

item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!

item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 361, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!

item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!

item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 362, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!

item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!

item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 363, Local, Stock NON VIP

Failed item 15. "Brake pad installed per plans, Photos 7.1 & 7.4". Reason -> Need Lock Washers

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!

item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!

item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 364, Local, Stock NON VIP

Failed item 6. "Steering hardware per plans, Photos 4.6, 4.10(a) & (b) ". Reason -> Need "R" washer

Failed item 13. "Bushing installed per plans, Photos 6.7". Reason -> Rear bolts upside down - Radius rods wrong bolts

Failed item 17. "Brake pedal hardware per plans, Photos 8.4, 8.12 & 8.18 ". Reason -> not per plan - needs lock washer - needs "R" washer on brake pedal

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!

item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!

item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 365, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!

item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!

item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 366, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!

item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!

item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 367, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!

item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!

item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 368, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!

item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!

item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = 369, Local, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!

item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!

item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
