

Car No. = R700, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R701, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R702, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R703, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R705, Rally, Stock NON VIP

Failed item 9. "Axle eyebolt per plans, Photo 5.13 ". Reason -> needs nut & lock w & eye bolt per planasher

Failed item 14. "Stock radius rod assembly per plans, Photos 6.16, 6.19, 6.23 & 6.26 ". Reason -> need lock washer on rod bolts

- Failed item 24. "Fixed weight hardware per plans, Photo 1.6". Reason -> cut weight bolts
 - item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R709, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R710, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R712, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R713, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R714, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R716, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R717, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R718, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!

item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R719, Rally, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R720, Rally, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R721, Rally, Stock NON VIP

Failed item 16. "New brake pad installed, ". Reason -> Needs brake pad
item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R723, Rally, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R724, Rally, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R725, Rally, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R726, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R727, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R728, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R729, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R730, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R731, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R732, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!

item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R733, Rally, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R734, Rally, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R736, Rally, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R737, Rally, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R738, Rally, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R739, Rally, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R740, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R741, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R742, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R743, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R744, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R745, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R746, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!

item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R747, Rally, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R748, Rally, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R749, Rally, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R750, Rally, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R756, Rally, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R757, Rally, Stock VIP But the following will be checked after shell installation

item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!

Car No. = R758, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R760, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R761, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R762, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
 - item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
 - item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!
-

Car No. = R763, Rally, Stock VIP But the following will be checked after shell installation

- item 30. "Screw in nose of the shell, Photo 12.11". Reason -> Check after body installed !!
- item 31. "Shell flush with bottom of floorboard , ". Reason -> Check after body installed !!
- item 32. "Shell circumference of 39-1/2 inches, ". Reason -> Check after body installed !!